



Traditionally, multiple piezometer installations in a borehole was slow, complex, and subject to unintended communication between piezometers. Grouted piezometers are quick and easy to install, have excellent zone isolation, and have rapid response to pore pressure changes. The fully grouted method is increasingly the preferred standard approach for installing piezometers in boreholes. For more information see:

McKenna, G.T. (1995), "Grouted-in Installation of Piezometers in Boreholes," Canadian Geotechnical Journal, Volume 32, pp 355-363.

Contreras, I.A. Grosser, A.T., VerStrate, R.H. (2007), "The Use of the Fully-grouted Method for Piezometer Installation". Proceedings of the Seventh International Symposium on Field Measurements in Geomechanics. FMGM, 2007. Boston, MA. ASCE Geotechnical Special Publication 175.

Also published in: Geotechnical News, June 2008, Vol. 26, No.2, [http://www.bitech.ca/pdf/GeoTechNews/2008/GIN\\_June08.pdf](http://www.bitech.ca/pdf/GeoTechNews/2008/GIN_June08.pdf)

Contreras, I.A. Grosser, A.T., VerStrate, R.H. (2011), "Practical Aspects of the Fully-Grouted Method for Piezometer Installation", Proceedings of the Eighth International Symposium on Field Measurements in Geomechanics. FMGM, 2011. Berlin, Germany, September 12-16, 2001

For further references and information regarding grout mixes, contact RST Instruments Ltd.

	<b>PRODUCT CATEGORY:</b>
	PIEZOMETERS + TRANSDUCERS

# Fully Grouted Multi-Point Piezometer String

Fully grouted installation permits multiple piezometers to be simply and reliably installed in a single borehole. The piezometer string and grout pipe are placed in the borehole and cement-bentonite grout is pumped until the borehole is filled.

Multi-point Piezometer Strings allow for multiple Vibrating Wire Piezometers to be connected on a single cable. This facilitates the installation of fully grouted multiple piezometers. The single cable prevents vertical void channels. Tough urethane-jacketed, Kevlar® reinforced, non-stretch cable is employed to withstand the rigors of installation and is entirely water-blocked to minimize any leakage. No conductors are shared to maximize independent reliability of each sensor.

RST Vibrating Wire Piezometers provide excellent long-term accuracy, stability of readings, and reliability under demanding geotechnical conditions. Vibrating Wire Piezometers are the electrical piezometers of choice as the frequency output of vibrating wire devices is immune to external electrical noise and able to tolerate wet wiring common in geotechnical applications.

## > APPLICATIONS

Ideal when more than one piezometer reading is needed at various depths at the same location.

### Assessing performance and investigating stability of:

Earth fill dams & embankments.	Slope stability.
--------------------------------	------------------

### Monitoring of:

Pressures behind retaining walls and diaphragm walls.	Pore pressure in land reclamation applications.
Pore pressures during fill or excavation.	

## > FEATURES

No inter-zone leakage.	Straightforward installation.
Field proven reliability and accuracy.	Immune from external electrical noise.
Will tolerate wet wiring common in geotechnical applications.	Cable lengths may be changed without affecting the calibration.
Thermistor for temperature measurement is standard.	Hermetically sealed, stainless steel construction.
Heavy case to minimize reading errors caused by overburden pressure.	Negligible displacement of pore water during the measurement process.
Signal transmission of several kilometers.	Data logger compatible.
Integral lightning protection.	

## > BENEFITS

✓ <b>Increase Safety</b>	✓ <b>High Accuracy</b>
✓ <b>Increase Productivity</b>	✓ <b>High Reliability</b>
✓ <b>Custom Options</b>	

WORKS WITH

READY TO RUN

- pre-assembled
- pre-wired
- pre-tested
- pre-programmed

\*Kevlar® is a registered trademark of E.I. duPont de Nemours and Company or its affiliates. RST Instruments Ltd. reserves the right to change specifications without notice. MIB0051D

# Fully Grouted Multi-Point Piezometer String



PRODUCT CATEGORY:  
PIEZOMETERS + TRANSDUCERS

## SPECIFICATIONS + ORDERING

### VIBRATING WIRE PIEZOMETER SPECIFICATIONS

The following specifications are for an individual vibrating wire piezometer.

DESCRIPTION	SPECIFICATION
Over range	2 X F.S.
Resolution	0.025% F.S. minimum
Accuracy	0.1% F.S.
Operating Temperature	-20 to 80°C (-4 to 176°F)
Diaphragm Displacement	<0.001 cc at F.S.
Thermal Zero Shift	<0.05% F.S./°C
Materials	Hermetically sealed stainless steel housing
Thermistor Type	NTC 3K 0hms @ 25°C
Thermistor Interchangeability	±0.2°C (optional ±0.1°C)
Thermistor Resolution	0.1°C
Filter	50 micron sintered filter. (High air entry alumina filter 1, 3, 5 Bar available)

### ELECTRICAL CABLE SPECIFICATIONS

PART #	DESCRIPTION
EL380012	12 conductor, Kevlar® wire with water-blocked polyurethane jacket
EL380013P	13 pair, Kevlar® wire with water-blocked polyurethane jacket
EL380052	26 pair, Kevlar® wire with water-blocked polyurethane jacket

Other types of cables, depending on site conditions, are available upon request.

### ORDERING INFO

PART #	DESCRIPTION	PRESSURE RANGES	DIMENSION
Due to the semi-custom nature of Multi-Point Piezometer Strings, please contact RST Instruments for complete ordering info. Ordering info will be dependent on required cable depth, number of piezometers per string and measurement parameters regarding pressure and/or temperature.			
VW2100MP-XXXX	Multi-point Piezometer String	0.35, 0.7, 1.0, 2.0, 3.0, 5.0, 7.0, and 10.0 MPa (Standard model vibrating wire piezometer ranges shown).	Dimensions dependent on cable and pressure ranges chosen.

### OPTIONAL EQUIPMENT

VW2106 Vibrating Wire Readout
Data loggers
Terminal stations
Electrical cable
Cable grip
VW2100-WT Weight Adapter

\*Kevlar® is a registered trademark of E.I. duPont de Nemours and Company or its affiliates. RST Instruments Ltd. reserves the right to change specifications without notice. MIB00051D

